

PAT TEST REPORT / CERTIFICATE

Client: Kabooth AKA Kristof Photography Address: Walsall Test equipment used: METREL GAMMAPAT 3311 Date 30/06/2025 Tested by GERRY BEVAN				NOTE NO: 2025001		
REGISTER NO.	LOCATION	DESCRIPTION	TYPE OF TEST		RESULT	NEXT TEST DUE
			VI	CI&T		
676	CONTAINER	RUSTIC FLASH IEC		a	PASS	Jun-2026
677	AS ABOVE	RUSTIC POWER BLOCK		a	PASS	Jun-2026
678	AS ABOVE	IEC		a	PASS	Jun-2026
679	AS ABOVE	PC POWER LEAD		a	PASS	Jun-2026
680	AS ABOVE	CANON LEAD	a		PASS	Jun-2026
681	AS ABOVE	BLACK IEC		a	PASS	Jun-2026
682	AS ABOVE	BRAIDED IEC		a	PASS	Jun-2026
683	AS ABOVE	4 GANG EXT LEAD		a	PASS	Jun-2026
684	AS ABOVE	2 GANG EXT LEAD		a	PASS	Jun-2026
685	AS ABOVE	HEART CAMERA LEAD	a		PASS	Jun-2026
686	AS ABOVE	HEART LED LIGHT	a		PASS	Jun-2026
687	AS ABOVE	HEART MONITOR IEC		a	PASS	Jun-2026
688	AS ABOVE	HEART FLASH IEC		a	PASS	Jun-2026
689	AS ABOVE	OVAL LIGHTS	a		PASS	Jun-2026
690	AS ABOVE	OVAL MONITOR PSU		a	PASS	Jun-2026
691	AS ABOVE	HAIR DRYER	a		PASS	Jun-2026
692	AS ABOVE	IEC		a	PASS	Jun-2026
693	AS ABOVE	IEC		a	PASS	Jun-2026
694	AS ABOVE	FIG 8 LEAD	a		PASS	Jun-2026
695	AS ABOVE	FIG 8 LEAD	a		PASS	Jun-2026
696	AS ABOVE	IEC		a	PASS	Jun-2026
697	AS ABOVE	FIG 8 LEAD	a		PASS	Jun-2026
698	AS ABOVE	PC POWER LEAD		a	PASS	Jun-2026
699	AS ABOVE	IEC		a	PASS	Jun-2026
700	AS ABOVE	IEC		a	PASS	Jun-2026
701	AS ABOVE	IEC		a	PASS	Jun-2026
702	AS ABOVE	CLOVER LEAD		a	PASS	Jun-2026
703	AS ABOVE	FIG 8 LEAD	a		PASS	Jun-2026
704	AS ABOVE	FIG 8 LEAD	a		PASS	Jun-2026
705	AS ABOVE	FIG 8 LEAD	a		PASS	Jun-2026
706	AS ABOVE	1 GANG EXT LEAD		a	PASS	Jun-2026
707	AS ABOVE	1 GANG EXT LEAD		a	PASS	Jun-2026

DEFINITIONS

VI = VISUAL INSPECTION OF PLUG, FLEX AND EQUIPMENT HOUSING

CI&T = COMBINED INSPECTION AS ABOVE AND TEST

PASS = THE EQUIPMENT SPECIFIED HAS PASSED THE RELEVANT SAFETY TEST / INSPECTION FAIL = THE EQUIPMENT SPECIFIED HAS FAILED THE RELEVANT SAFETY TEST / INSPECTION

MISSING = THE ITEM WAS UNABLE TO BE LOCATED AT TIME OF TEST

PAT TEST REPORT / CERTIFICATE